

# Energy performance certificate (EPC)

Unit 1 Brook Park Gaddesby Lane Rearsby LEICESTER LE7 4ZB	Energy rating <b>D</b>	Valid until: <b>19 April 2029</b> Certificate number: <b>0570-0231-9739-7194-2006</b>
---	---------------------------	--

**Property type**  
B1 Offices and Workshop businesses

**Total floor area**  
73 square metres

**Rules on letting this property**

Properties can be let if they have an energy rating from A+ to E.


If a property has an energy rating of F or G, the landlord cannot grant a tenancy to new or existing tenants, unless an exemption has been registered.

From 1 April 2023, landlords will not be allowed to continue letting a non-domestic property on an existing lease if that property has an energy rating of F or G.

You can read [guidance for landlords on the regulations and exemptions](https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment_data/file/824018/Non-Dom_Private_Rented_Property_Minimum_Standard_-_Landlord_Guidance.pdf) ([https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment\\_data/file/824018/Non-Dom\\_Private\\_Rented\\_Property\\_Minimum\\_Standard\\_-\\_Landlord\\_Guidance.pdf](https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment_data/file/824018/Non-Dom_Private_Rented_Property_Minimum_Standard_-_Landlord_Guidance.pdf)).

**Energy efficiency rating for this property**

This property’s current energy rating is D.



Properties are given a rating from A+ (most efficient) to G (least efficient).

Properties are also given a score. The larger the number, the more carbon dioxide (CO2) your property is likely to emit.

### How this property compares to others

Properties similar to this one could have ratings:

#### If newly built

32 | B

#### If typical of the existing stock

95 | D

### Breakdown of this property's energy performance

#### Main heating fuel

LPG

#### Building environment

Heating and Natural Ventilation

## Assessment level

3

---

## Building emission rate (kgCO<sub>2</sub>/m<sup>2</sup> per year)

72.48

---

## Primary energy use (kWh/m<sup>2</sup> per year)

419

---

► [What is primary energy use?](#)

## Recommendation report

Guidance on improving the energy performance of this property can be found in the [recommendation report \(/energy-certificate/0940-7972-0431-9510-2070\)](/energy-certificate/0940-7972-0431-9510-2070).

## Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

## Assessor contact details

### Assessor's name

T Taylor

---

### Telephone

07595712683

---

### Email

[tara@fepenergy.co.uk](mailto:tara@fepenergy.co.uk)

---

## Accreditation scheme contact details

### Accreditation scheme

Elmhurst Energy Systems Ltd

---

### Assessor ID

EES/008121

---

**Telephone**

01455 883 250

---

**Email**

[enquiries@elmhurstenergy.co.uk](mailto:enquiries@elmhurstenergy.co.uk)

---

**Assessment details**

**Employer**

Future Energy Performance

---

**Employer address**

3&5 Ibstock Road, Ellistown 01530 453940

---

**Assessor's declaration**

The assessor is employed by the organisation dealing with the property transaction.

---

**Date of assessment**

15 April 2019

---

**Date of certificate**

20 April 2019

---

**Other certificates for this property**

If you are aware of previous certificates for this property and they are not listed here, please contact us at [dluhc.digital-services@levellingup.gov.uk](mailto:dluhc.digital-services@levellingup.gov.uk) or call our helpdesk on 020 3829 0748.

There are no related certificates for this property.